Robotics Service Bus - Bug #714 Bus-lock in socket-based transport is too coarse

11/10/2011 12:47 PM - J. Moringen

Status: Resolved Start date: 11/10/2011

Priority: Normal Due date:

Assignee:J. Moringen% Done:100%Category:Common LispEstimated time:0.00 hour

Target version:

Description

Deadlocks can happen when events are simultaneously sent and received while racing for an additional lock in both threads.

Bummer.

Related issues:

Related to Robotics Service Bus - Feature # 711: Implement socket-based trans... Resolved 11/10/2011

Associated revisions

Revision 816559ca - 12/14/2011 03:32 AM - J. Moringen

initial merge of changes from socket-transport branch fixes #714, refs #711

History

#1 - 12/14/2011 03:40 AM - J. Moringen

- Status changed from New to Resolved
- % Done changed from 0 to 100

Applied in changeset r3172.

04/23/2024 1/1