

Robotics Service Bus - Feature #543

Explore Correct Flags for Compilation under RoBoard with Ubuntu Lucid

09/05/2011 11:06 AM - S. Wrede

Status:	Rejected	Start date:	09/05/2011
Priority:	High	Due date:	
Assignee:		% Done:	0%
Category:	Configuration	Estimated time:	2.00 hours
Target version:			

Description

Currently, using the defaults, an invalid instruction set error arises if RSB components are copied and executed directly to the RoBoard.

This is important to speed up development and find a good deployment strategy for embedded RSB components.

History

#1 - 10/21/2011 05:07 PM - S. Wrede

- Status changed from New to Rejected

Please move this ticket to the AMARSi Software Architecture trackers.