

Robot Control Interface - Bug #893

Copy constructor of Pose is not working

02/20/2012 07:31 PM - C. Emmerich

Status:	Resolved	Start date:	02/20/2012
Priority:	High	Due date:	
Assignee:		% Done:	100%
Category:		Estimated time:	0.00 hour
Target version:			
Description			
<p>Copy constructor of Pose is not working because either</p> <ul style="list-style-type: none">- copy constructor is implemented wrong- or some issues with the inheritance of (<code>_transl</code> and <code>_rot</code>) from <code>CartesianValue</code>			

Associated revisions

Revision 553 - 02/24/2012 06:07 PM - anordman

Fixed and tested all pose constructors
fixes #893

History

#1 - 02/24/2012 06:10 PM - Anonymous

- *Status changed from New to Resolved*
- *% Done changed from 0 to 100*

Applied in changeset r553.